## NM 29/04

## SECTION II NAVIGATION PUBLICATIONS

## SAILING DIRECTIONS CORRECTIONS

<b>PUB 127</b> (NGA)	8 Ed 2004	NEW EDITION 29/04
<b>PUB 155</b> (NGA)	8 Ed 2004	NEW EDITION 29/04
<b>PUB 157</b> (NGA)	10 Ed 2004	NEW EDITION 29/04
<b>PUB 191</b> (NGA)	11 Ed 2004	NEW EDITION 29/04

## COAST PILOT CORRECTIONS

COAST PILOT 9 21 Ed 2003 Change No. 28 LAST NM 28/04

Page 127—Paragraph 106, lines 2 to 3; read:

the E sandspit to a  $1\sqrt[3]{4}$ -fathom spot in  $59^{\circ}55'43"N$ .,  $141^{\circ}25'54"W$ . Depths to the N of the shoal are greater ... (BP 183151; H-10985) 29/04

Page 127—Paragraph 107, lines 2 to 6; read:

side of Riou Bay. A bar, with a least depth of  $^{3}/_{4}$ -fathom, NW of Moraine Island, extends from 59°55'57"N., 141°23'37"W. to 59°56'01"N., 141°23'53"W. A shallow but navigable channel exists between the  $^{3}/_{4}$ -fathom bar and a  $^{1}/_{4}$ -fathom spot about 0.5 mile to the E. A temporary ...

(BP 183151; H-10985) 29/04

Page 127—Paragraph 108, line 3; read:

NE end of the island is conspicuous. A shoal extends 1 ... (BP 183151; H-10985) 29/04

Page 127—Paragraph 114, lines 5 to 8; read:

may yield in very high winds. In 2000, the controlling depth in the NW part of the harbor was 4 fathoms with a  $1\frac{1}{4}$ -fathom spot at the entrance in 59°56′00"N.,  $141^{\circ}22'45$ "W. Do not anchor between Moraine Island ...

(BP 183151; H-10985) 29/04

Page 233—Paragraph 1415, line 7; read:

Ship Creek side of the dock.

**Port MacKenzie Dock:** (61°16'05"N., 149°55'01"W.), on the W shore of Knik Arm, 1.3 mile WNW of Cairn Point; 500-foot face; 20 feet alongside; deck height, 36 feet; filter rock ramp; 8,000 acres of open storage; water, electricity; highway connections; receipt of bulk commodities, containerized cargo, iron and steel materials, petroleum products, vehicles and heavy equipment, and modular buildings. Owned and operated by the Matanuska-Susitna Burough.

(CL 795/04; BP 172712) 29/04

Page 473—Paragraph 618, lines 10 to 12; read:

above the mouth of the Snake River. A small boat harbor is at the N end of the turning basin. In June 2002-August 2003, the controlling depth was 7.1 feet to the basin, thence 6.6 to 8 feet in the basin with lesser ...

(CL 654/04; BP 181853; BP 181401) 29/04

II-2.1